FPA Notification c. Hazardous Waste Site

United States Environmental Protection Agency Washington DC 20460

			_			
3	This initial notification information is required by Section 103(c) of the Comprhensive Environmental Response, Compation, and Liability Act of 1980 and mube mailed by June 9, 1981.	en- paper Indicate the let est which applies.	separate sheets of etter of the item 810609			
	·	IL # 0	232 115-000-001-493			
Α	Person Required to Notify:	Arc Dispos	sal Co. Inc. (TRANSPORTER)			
	Enter the name and address of the person	on Name				
	or organization required to notify.	Street 5859 N. Ri	ver ka.			
	\ \	City Rosemont,	III. 60018 State Zip Code			
B	Site Location:					
	Enter the common name (if known) and	Name of Site Uninco	orporated Wheeling, Ill.			
	actual location of the site.	_{Street} off Milwau	Street off Milwaukee Ave. & North of Wolf Rd.			
	120 980612550	CITY WHEEL/I	NG County COOK State []]. Zip Code 60090			
C	Person to Contact:					
	Enter the name, title (if applicable), and business telephone number of the persoto contact regarding information submitted on this form.	Name (Last, First and Title) On Phone Unknown	unknown			
D	Dates of Waste Handling:					
	Enter the years that you estimate waste treatment, storage, or disposal began an ended at the site.	To (Year) 1970				
 E	Waste Type: Choose the option you prefer to complete					
_						
	Option I: Select general waste types an you do not know the general waste type encouraged to describe the site in Item I	s or sources, you are	Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 300 regulations (40 CFR Part 261).			
		ce of Waste: an X in the appropriate i.	Specific Type of Waste: EPA has assigned a four-digit number to each hazardous was listed in the regulations under Section 3001 of RCRA. Enter appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the sit			
	1. ☐ Organics 1. ☐	Mining	located.			
		Cönstruction				
		Textiles				
	4. ☐ Pesticides 4. ☐	Fertilizer				
	5. ☐ Heavy metals 5. ☐	Paper/Printing				
		Leather Tanning				
		Iron/Steel Foundry				
		Chemical, General				
		Plating/Polishing				
		Military/Ammunition				
		Electrical Conductors				
	12. ☐ Transformers					
		Utility Companies	00005 JUN -9°81			
		Sanitary/Refuse	JUN -9"81			
	· · · ·	Photofinish				
		Lab/Hospital	EPA Pagion 5 Pagarde Ctr			
		Unknown	EPA Region 5 Records Ctr.			
		Other (Specify)				
		···-	358357			

JUN 1 0 1981

Form Approved OMB No. 2000-0138

	Notification of Hazardous Waste, ste	Side Two					
F	Waste Quantity:	Facility Type	Total Facility Waste A	meunt			
	Place an X in the appropriate boxes to indicate the facility types found at the site.	1. ☐ Piles	cubic feet				
	In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.	□ Land Treatment □ Landfill	gallons	<u> </u>			
		4. 🗆 Tanks	Total Facility Area				
		5. Impoundment6. Underground Injection	square feet				
	In the "total facility area" space, give the estimated area size which the facilities	7. Drums, Above Ground	acres				
	occupy using square feet or acres.	8. ☐ Drums, Below Ground 9. ☐ Other (Specify)					
G	Victoria Supported at Likely Polysper 1						
G	Known, Suspected or Likely Releases to the Environment: Place an X in the appropriate boxes to indicate any known, suspected, □ Known □ Suspected □ Likely □ None						
	or likely releases of wastes to the environme		_ mom _ copenie	_ _			
	Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.						
H	Sketch Map of Site Location: (Optional	al)		•			
	Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.	•					
		N.					
	•						
$\overline{}$	Description of Site: (Optional)						
	Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which						
•	may help describe the site conditions.						
_							
J	Signature and Title:	Arc Disposal Co. Inc.					
	(such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing	5859 N. River Rd.		Owner, Present			
		Street Rosemont, III. 60018		Owner, Past Transporter			
		City	7in Codo	Operator, Present			
		City State		Operator, Past Other			
	relationship to the site of the person required to notify. If you are not required to notify check "Other".	Signature Jan Jane ga	Date 6/8/8/	Other			



United States Environmental protection agency Region V

111 West Jackson Blvd. CHICAGO, ILLINOIS 60604

REPLY TO ATTENTION OF:

Date 9	7-1-81			
Reference	No. 165-	000-	001-9	794
	165-	000	001-4	493

Dear Superfund Notification Respondent:

The U.S. Environmental Protection Agency (EPA) has received the information you filed pursuant to Section 103(c) of the Comprehensive Environmental Response, Compensation and Liability Act (Superfund). We are hereby returning this document for the following reason:

- Essential information is missing or illegible.
 Red circles indicate such items.
- It cannot be determined whether your notification was legally required or whether you were not required to report the site for which you notified.
- /// You failed to sign and/or date the document.

Please provide the information requested either on the original document or on the blank form enclosed herein. Return the original document, this letter, and the new form if (necessary) no later than 9-30-81 to:

U.S. EPA, Region V Sites Notification 111 W. Jackson Blvd. Chicago, IL 60604

Your notification will be regarded as late if you do not resubmit this information by the above date. If you have any questions on providing this information, please call: (312) 886-6391.

1881 80 458


Sincerely yours,

Regional Project Officer

Oak

SEP 0 8 1981

y: 15



U.S. E.P.A. REGION 5 III W. Jackson Blvd SITES NOTIFICATION 16th Floor CHICAGO, ILL, 60501